

# CERTIFICATE

This is to certify that the

**ENERGY MANAGEMENT SYSTEM**

of **ELECTROPOLI Czech Republic, s.r.o.**

Budovatelů 482  
538 43 Třemošnice, Czech Republic

**electropoli**  
CZECH REPUBLIC

has been found compliant with the requirements of the energy management system guideline

**EN ISO 50001:2011**

Scope of certification:

**PRODUCTION OF SURFACE TREATED PARTS.**

Certification Date: 12 January 2016

Certificate valid to: 12 January 2019



Mgr. Petr Požár  
CEO



Place and Date of Issue:  
Prague, 12 January 2016



The list of branches belonging to the system of control is presented in the independent appendix of this certificate.  
Not complying with the conditions of certification stated at [www.tcert.cz](http://www.tcert.cz) may lead to invalidity of the certificate.

**This appendix is an integral part of certificate no. 005/2016 issued by ELECTROPOLI Czech Republic, s.r.o., Company ID no.: 62063685**  
If the certificate is presented, this appendix must also be presented.

The management system of ELECTROPOLI Czech Republic, s.r.o. is applied in the following branches and/or business premises of the certified client.

These branches and/or business premises can use the management system certification in accordance with the conditions specified in Conditions of use of T Cert certification labels, available at [www.tcert.cz](http://www.tcert.cz).

Company seat	The range of activities and services, scopes	Note
Budovatelů 482 538 43 Třemošnice Czech Republic	Production of surface treated parts.	Head office

Branch address	The range of activities and services, scopes	Note
Budovatelů 482 538 43 Třemošnice Czech Republic	Production of surface treated parts.	Branch office
Husova 168/3 463 43 Český Dub Czech Republic	Production of surface treated parts.	Branch office

**Please note:**

Any branches and/or business premises of the certified client, which are not included in the management system, cannot present themselves as being part of that system. Any unauthorised use of the T Cert certification label shall result in a suspension of the certification until the problem has been solved by the client. Failure to abide by these rules may lead to a withdrawal of the certification.

Prague, 12.1.2016



Mgr. Petr Požár  
CEO